Cisco IP Phone 8800 Release Notes for Firmware Release 14.2(1)SR1

June 27, 2023

© 2022 Cisco and/or its affiliates. All rights reserved.

Contents

Cisco IP Phone 8800 Series Release Notes for Firmware Release 14.2(1)SR1 3
New and Changed Features 3
Features Available with the Firmware Release 3
Caveats 3
View Caveats 3
Cisco IP Phone Firmware Support Policy 4

© 2023 Cisco and/or its affiliates. All rights reserved.

Cisco IP Phone 8800 Series Release Notes for Firmware Release 14.2(1)SR1

These release notes support the Cisco IP Phone 8811, 8841, 8845, 8851, 8851NR, 8861, 8865, and 8865NR running SIP Firmware Release 14.2(1)SR1.

New and Changed Features

Features Available with the Firmware Release

The following sections describe the features available with the Firmware Release.

Multi-server (SAN) Tomcat Certificate with Cisco UCM

Starting from this release, the phone supports Cisco UCM with Multi-server (SAN) Tomcat Certificates configured. The TFTP server address can still be found in the phone ITL file.

This feature requires:

- Cisco Unified Communication Manager Release: 14 or later

Where to Find More Information

- *How To Configure Multi-server (SAN) Tomcat certificate with Cisco UCM*
- *Security Guide for Cisco Unified Communications Manager Release 14 and SUs*
- *Cisco IP Phone 8800 Series Administration Guide*

Localization Improvement on Enhanced Survivability

The feature Enhanced Survivability only applies to **Webex Calling Dedicated Instance**. Since from this release, the phone improves the localization support on this feature. The supported languages can be referred to Cisco IP Phone 8800 Series Data Sheet.

Where to Find More Information

- *Enhanced Survivability for Webex Calling Dedicated Instance*

S6 Enhancement

- CSCuv46831 Improve NTP accuracy

Caveats

View Caveats

We report open and resolved customer-found bugs of severity 1 to 3. You can find details about listed bugs and search for other bugs by using the Cisco Bug Search Tool. For more info on using the Bug Search, see Bug Search Tool Help.

- Use this URL for all caveats: https://bst.cloudapps.cisco.com/bugsearch/search?kw=*&pf=prdNm&pfVal=284729655&rls=14.2(1)SR1&sb=anfr&svr=3nH&bt=custV

© 2023 Cisco and/or its affiliates. All rights reserved.

- Use this URL for all open caveats: https://bst.cloudapps.cisco.com/bugsearch/search?kw=*&pf=prdNm&pfVal=284729655&rls=14.2(1)SR1&sb=afr&sts=open&svr=3nH&bt=custV
- Use this URL for all resolved caveats:

  https://bst.cloudapps.cisco.com/bugsearch/search?kw=*&pf=prdNm&pfVal=284729655&rls=14.2(1)SR1&sb=fr&sts=fd&svr=3nH&bt=custV

Cisco IP Phone Firmware Support Policy

For information on the support policy for phones, see https://cisco.com/go/phonefirmwaresupport.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at **https://www.cisco.com/go/offices**.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2023 Cisco and/or its affiliates. All rights reserved.