GV-SNVR3203/6403 Version History

Firmware V1.01 2023-06-21

Firmware V1.01 applies to the following GV-SNVR models:

- GV-SNVR3203
- GV-SNVR6403

Fixed:

- Failure to resume Motion Detection function when IP cameras are connected via ONVIF protocol after reboot
- Connection failure to GV-Edge Recording Manager when the HTTP port is not set to 80
- Failure to switch to third stream for all channels on the Web interface when the IP cameras are connected via ONVIF protocol
- Issue of scrambled Web plugin display for operating systems in certain languages
- Audio function and audio input selection failure when connected to GV-IP cameras
- Chances of operation failure
- Audio failure when Wave Out and Microphone functions are enabled on GV-Edge Recording Manager
- Failure to connect to GV-Eye using relay QR code when RTSP port is changed on GV-SNVR3203/6403
- Issue of system erasing all settings and recording data on the NVR set as the hot spare device without a warning message
- Chances of inability of switching on Mobile APP function

Improved:

- Invalid options removed from the Web interface
- Serial configuration interface removed
- Warning message display added when NIC1 and NIC2 are set in the same network segment