

This document describes the features, operational issues, and major fixes for the Pelco Fisheye cameras. Review each section to determine if an upgrade is warranted for your installation. For additional information on the camera (including the latest updates to documentation, product specifications, and software downloads), visit the Pelco Web site at www.pelco.com.



Note: For technical issues, contact Pelco Product Support at 1-800-289-9100 (USA and Canada) or +1-559-292-1981 (international).

To upgrade the camera, there are two methods and you use a different file depending on the process.

- To update your camera using the camera's web interface, use the firmware file with the .BIN extension.
- To update your camera using the Camera Configuration Tool, use the firmware file with the .FWP extension.

4.66.0.26 Release

New Feature and Improvements

- The feature to disable analytics has been renamed to "No Video Analytics," rather than "No Smart Analytics," within the WebUI.

Major Fixes

- Fixed an issue that could cause an incorrect URL redirection.

4.60.0.30 Release

Major Fixes

- Fixed a problem where the camera could continuously reboot if configured to use Dewarp Streaming 180x2 mode and an overlay is enabled.

4.60.0.24 Release

New Features and Improvements

- Added a "No Smart Analytics" option in the WebUI to allow the user to disable Smart Analytics functionality.
- The camera is now compliant with the ONVIF Profile M specification.

Major Fixes

- Fixed a problem where the camera WebUI could fail to load in Mac OS web browsers.

4.44.0.14 Release

Major Fixes

- Fixed an issue where a temporary network disruption to the associated VMS or NTP service may cause cameras to stop streaming video within the VMS.

Pelco Fisheye v 4.66.0.26 Release Notes

- Fixed an issue where cameras may fail to adjust to Daylight Savings Time within the IST/IDT time zone.

4.44.0.12 Release

New Features

- Added support for ONVIF Profile M.
- Added a display showing whether the internal microphone is enabled or disabled in the Web user interface.

Major Fixes

- Fixed an issue where analytics bounding boxes appeared in incorrect positions.
- Fixed an issue where the option to configure vehicle detection analytic was missing.

4.18.0.122 Release

Major Fixes

- Improved the internal logging capabilities of the camera.

Pelco Fisheye v 4.66.0.26 Release Notes



Pelco, Inc.
625 W. Alluvial Ave., Fresno, California 93711 United States
(800) 289-9100 Tel
(800) 289-9150 Fax
www.pelco.com

Pelco, the Pelco logo, and other trademarks associated with Pelco products referred to in this publication are trademarks of Pelco, Inc. or its affiliates. ONVIF and the ONVIF logo are trademarks of ONVIF Inc. All other product names and services are the property of their respective companies. Product specifications and availability are subject to change without notice.

© Copyright 2023, Pelco, Inc. All rights reserved.