APC™ Smart-UPS™ Modular Ultra Power Distribution Unit (PDU)


NOTE: SRYLPD1 is used for the purpose of illustration. The process is applicable to all PDUs.

DANGER

RISK OF ELECTRIC SHOCK

- · PDUs should be replaced only by a qualified electrician.
- Switch off the electrical panel circuit breaker before attempting to replace the PDUs.
- Be sure that either the Power Distribution Unit (PDU) or the PDU blanking panel is positioned correctly and secured before connecting the unit to AC Mains.

Failure to follow these instructions will result in death or serious injury.



Schneider Electric

35 rue Joseph Monier 92500 Ruel Malmaison - France Phone: +33 (0) 1 41 29 70 00

Phone: +33 (0) 1 41 29 70 00 www.apc.com

As standards, specifications, and design change from time to time, please ask for confirmation of the information given in this publication.

© 2022 Schneider Electric. All rights reserved.

