


RS5100 Corded Adapter Quick Start Guide

The Corded Adapter connects an arm or wrist-mounted host terminal to the RS5100 in order to provide power to the scanner. Data communication between the host and scanner is provided via Bluetooth, not through the adapter.

CBL-RS5X6-ADPWT-01

Accommodates connection to the WT6X00.



CBL-RS5X6-ADPTC-01

Accommodates USB-C connection to the TC21/TC26 and TC53/TC58.

