


RS5100/RS6100 Corded Adapter Quick Start Guide

The Corded Adapter connects an arm or wrist-mounted host terminal to the RS5100 or RS6100 in order to provide power to the scanner. Data communication between the host and scanner is provided via Bluetooth, not through the adapter.


CBL-RS5X6-ADPWT-01

Accommodates connection to the WT6X00.



CBL-RS5X6-ADPTC-01

Accommodates USB-C connection to the TC21/TC26 and TC53/TC58.



MN-004607-02EN

12/22