



FER-PLAQUE VIS7/8X10TRQ




2

16




** IMPORTANT/IMPORTANTE **

DO NOT TURN OVER SURFACE WITH THE HELP
OF THE BASES
NE PAS RETOURNER LA SURFACE À L'AIDE DES
BASES
NO VOLTEAR LA MESA AYUDÁNDOSE DE LAS
BASES




TO FACILITATE MANIPULATION, INSERT
A PIECE OF PACKAGING UNDER
SURFACE
POUR FACILITER LA MANUTENTION,
INSÉRER UN MORCEAU D'EMBALLAGE
SOUS LA SURFACE
PARA FACILITAR LA MANIPULACIÓN,
INSERTAR UN TROZO DE CARTÓN
DEBAJO DE LA SUPERFICIE








● PRC48____
■ PRC4896____
● POC48____
■ PRT4896____

1. INSTALL THE BASES ON SURFACE OR SURFACES
INSTALLER LES BASES SUR LA SURFACE OU LES SURFACES
INSTALAR LAS BASES EN LA(S) SUPERFICIE(S)



OR
OU



2. RETURN THE SURFACE OR RETURN THE SURFACES AND INSTALL
THEM TOGETHER
RETOURNER LA SURFACE OU RETOURNER LES SURFACES ET SI LES
INSTALLER ENSEMBLES
GIRAR LA(S) SUPERFICIE(S) E INSTALARLAS JUNTAS

