







497K18121 / 497K22640


AltaLink B8100/C8100	
VersaLink B70XX/C70XX VersaLink B71XX/C71XX	
VersaLink B405/C405	
VersaLink B605/B615 & VersaLink C505/C605	
PrimeLink B91XX	

AltaLink B8100/C8100 (1 of 2)

1.





2.








3.



4.




AltaLink B8100/C8100 (2 of 2)




VersaLink B70XX / B71XX / C70XX / C71XX (1 of 2)


1.




2.




3.





4.



5.




6.




VersaLink B70XX / B71XX / C70XX / C71XX (2 of 2)


7.




8.




9.




10.



11.




12.




VersaLink B405/C405 (1 of 2)


1.





2.



3.




4.




VersaLink B405/C405 (2 of 2)


5.




6.



7.




8.




VersaLink B605/B615

VersaLink C505/C605 (1 of 2)


1.




2.



3.




4.




VersaLink B605/B615 VersaLink C505/C605 (2 of 2)


5.




6.




7.




8.



9.




10.




PrimeLink B91XX (1 of 2)


1.




2.




3.



4.



5.




6.




PrimeLink B91XX (2 of 2)


7.




8.




9.




10.



11.



12.



This page left blank intentionally.